OUT 66649

18 DEC 68 20

117

DISTRIBUTION

FILE

SECUS

PSG/GG

RRD

repro raid

PROD SCIEN WEST EAST

Mas

IAS 5

DIA-XX4

IEU

OFFICE

GABLE, SEC

PP&B/ND

181948Z DEC 68 FM NPIC WASHDC TO RHCOAAA/SAC OFFUTT AFB OMAHA NEB RHCOAAA/544TH ARTW OFFUTT AFB OMAHA NEB RUCLFGA/100TH SRW OL 19 MCCOY AFB FLA RUWJDBA/100TH SRW DAVIS MONTHAN AFB ARIZ RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD RUEAIIA/CIA WASH DC RUEOJFA/DIA RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF RUEFHQA/HQS USAF BT S E C R E T CITE NPIC 5296.

SAC FOR DIR, DOSR, DISD; 15TH AF FOR DI, DO; 100TH SRW FOR CO. DCOI; HQ USAF FOR AFRDR COL. HARTLEY; DIA FOR DIAXX-2. FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

SUBJECT: EVALUATION OF GLASS LAMP MISSION G-057

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION good where not degraded by atmospherics. As reported on Misston- G-054, THERE IS A SLIGHT VARIATION IN IMAGE QUALITY ACROSS THE

PAGE 2 RUEADJU Ø111 S E C R E T FORMAT. THE IMAGERY NEAREST THE NON-DATA CHAMBER END IS OF BETTER QUALITY THAN THAT RECORDED NEAREST THE DATA CHAMBER END. THE GROUND RESOLUTION AND INTERPRETATION SUITABILITY ARE GOOD WHERE NOT DEGRADED BY ATMOSPHERICS. 2. MISSION DATA:

SPAD 10 DIA-AP A. THE STANDARD "B" CONFIGURATION CAMERA, UNIT NUMBER 10 WAS USED ON MISSION G-057, FLOWN ON 14 DECEMBER 1968. MODE 5 WAS 25X1 CMX USED THROUGHOUT THE MISSION.

B. FILM TYPE 3401 WAS USED WITH AN EXPOSURE OF 1/360 AT F/10. THE MATERIAL WAS PROCESSED TO AN AVERAGE GAMMA OF 2.43. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

3. ORIGINAL NEGATIVES:

ADVANCE CY A. EXPOSURE: THE EXPOSURE IS ADEQUATE THROUGHOUT THE MISSIAN TIZED B. DENSITY AND CONTRAST: GENERALLY MEDIUM WHERE NOT AFFECTED

BY ATMOSPHERICS.

C. IMAGE DEGRADATIONS:

(1) 9R SIDE: NEEDLE-SHAPED FOG PATTERNS, ASSOCIATED WITH CAMERA START-UP, ARE PRESENT ON FRAMES 1, 2, 6, AND 9. FORK-SHAPED FOG PATTERNS 1.5 INCHES LONG, EMINATING FROM THE OUTBOARD EDGE AND 1.0 INCH FROM THE NON-DATA BLOCK END OF THE FRAME. ARE PRESENT ON

PAGE 3 RUEADJU Ø111 S E C R E T FRAME 496. A PLUS DENSITY STREAK, 3.0 INCHES FROM THE INBOARD EDGE, BEGINS NEAR THE CENTER OF FRAME 1429 AND EXTENDS HALF WAY THROUGH FRAME 1430.

(2) 9L SIDE: A ROW OF MINUS DENSITY DOTS, 1.75 INCHES APART, 5.5 INCHES FROM THE INBOARD EDGE, IS PRESENT ON APPROXIMATELY THE FIRST 50 FRAMES. PROCESSING STREAKS ARE PRESENT ON THE LAST HALF OF THE MISSION.

(3) BOTH SIDES: ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE ON BOTH SIDES.

> E3636 8 Endrerd from externation dewhicading and



D. PHYSICAL DEGRADATIONS:

(1) BOTH SIDES: FIVE HEAT SPLICES AND ONE MANUFACTURING SPLICE ARE PRESENT ON THIS MISSION.

E. AUXILIARY DATA: THE EVENTS COUNTER WAS INOPERATIVE THROUGHOUT THE ENTIRE MISSION. ALL OTHER DATA RECORDING SYSTEMS FUNCTIONED PROPERLY.

F. THE LAST TITLED FRAME IS 2013.

4. POSITIVES: THE PRINTING AND PROCESSING ARE GOOD.

GP-1

SECRET

END OF MESSAGE